

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans Time 8:43 AM

Run date 22-Nov-14

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 488 Const Calendar Day: 661 Date: 27-Mar-2014 Thursday Inspector Name: Feather, Bernard Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 08:00 am 11:30 pm **Break:** 07:00 **Over Time:** 00:30

Federal ID: Location:

Reviewer: Shedd, Bill Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition overcast, cold

Working Day 🗸 If no, explain:

Diary:

General Comments

Weekly safety meeting 0800-0900. Misc MEP paperwork and write diaries. Track progress of FWS mechanical piping installation from a night closure of the #1 lane of the WB bridge.

 04-0120F4
 Bid Item:
 128
 0-000-000.128
 DEHUMIDIFIER SYSTEM

 F.W. SPENCER AND SON, INC

Diary:

East Anchorage 128 0-000-000.128

Dehumidification System

On 3/26/2014, Bill O'Sullivan sent an email stating that Certified Coatings needs to address paint punchlist items on the east side of the Eastbound cable anchorage compartment. They were planning to mobilize today and expect the work to be completed by the end of next week.

He asked what measures Certified Coatings needs to take in order to work in this area (i.e. shutdown dehumid unit, cover penetrations, etc.).

Bill was informed that the painters are to shut off the unit and cover the process air intake with plastic before they start work. At the end of the shift, before they leave, they are to remove the plastic over the intake, and turn the unit back on to "manual." This was later modified to shut down the units, cover the intakes with plastic, then keep the shut down and covered until the work is finished.

Anna Lee, Blayco, Sam Patel, CT, and Rocky Garcia, PB discussed the status of the humidistat/SCADA interface at the tower head.

CCO-187 Bid Item: 001 0-MSI-EFA.187 **MEP/Structural Interferences** F.W. SPENCER AND SON, INC Labor RT Hrs OT Hrs DT Hrs Total Remarks Dispute Trade Class Name Contractor: F.W. SPENCER AND SON, INC Welder JNM RICHARD KIIKVEE 8.00 8.00 0.00 0.00 Plumber/Pipefitter NARCISO BIAGI JNM. 8 00 0.00 0.00 8 00 Plumber/Pipefitter FOR TOM COLOMBO 8 00 0.00 0.00 8.00 Dispute Diary:

Daily Diary Report by Bid Item Inspector Name Feather, Bernard Job Name: 04-0120F4 Diary #: 488 Date: 27-Mar-2014 6" DIP Testing 0-MSI-EFA.187 001 The FWS crew, including Josh Johnson, intended to spend the shift assessing the leak in the 6" CCSF Reclaimed Water Main at CB 8, repair it, then test the piping. However, after disassembling the pipe at that location, it could not be reassembled due to interferences with the cross beam gate posts. Due to situations beyond FWS, this work is now considered CCO 187 work. The crew used a 2.5 HP generato and three crew trucks in performance of this operation. CCO-354 Bid Item: 001 0-FWS-ELS.354 CIC - Mechanical Impacts - F.W. Spencer F.W. SPENCER AND SON, INC Dispute Diary: **Mechanical Change of** 001 0-FWS-ELS.354 To perform the night's operations, the FWS crew worked from a closure of the #1 lane of the WB bridge. Mobilization to and from the bridge will be covered under CCO 187 for this shift. In addition to equipment used in the evening's operations, the crew used 2 additional crew trucks, a light tower, and a port-a-potty on a trailer.

